

OPTIONAL SERVICE BULLETIN

NO. OSB40-037

&

OPTIONAL SERVICE BULLETIN

NO. OSBD4-040

I. TECHNICAL DETAILS

1.1 Category

Optional.

1.2 Airplanes affected

DA 40: all, if not already installed during production
DA 40 D: all, if not already installed during production
DA 40 F: all, if not already installed during production

1.3 Time of Compliance

At owner's discretion.

1.4 Subject

Installation of the maintenance access holes in front seats.

ATA-Code: 25-00, Equipment and Furnishings

1.5 Reason

The optional installation of the maintenance access holes in front seats for reduced maintenance inspection effort.

1.6 Concurrent documents

None.

1.7 Approval

The information and instructions contained in this document relate to the Design Change Advisory OÄM 40-223 which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

1.8 Measures

Work Instructios No. WI-OSB40-037 (DA 40 and DA 40 F) or No. WI-OSBD4-040 (DA 40 D) must be complied with.

1.9 Mass (Weight) and CG

Negligible.

II. PLANNING INFORMATION

2.1 Material & Availability

All necessary parts with specific part numbers can be ordered from Diamond Aircraft Industries GmbH, Diamond Aircraft Industries Inc., or from your local General Distributor or Diamond Service Center. All other parts shall be procured locally.

2.2 Special Tools

No special tools are required.

2.3 Labor effort

Appr. 14 hours.

2.4 Credit

None.

2.4 Reference documents

Diamond Aircraft DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

III. REMARKS

1. All measures must be carried out by the manufacturer, a certified aircraft service station or a certified aircraft maintenance mechanic.
2. Accomplishment of the measures must be confirmed in the log book.
3. In case of doubt, contact Diamond Aircraft.