

OPTIONAL SERVICE BULLETIN

NO. OSBD4-048

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 40 D

Serial Numbers: 40.080, 40.084, D4.001 and subsequent

I.3 Time of Compliance

At owner's discretion

I.4 Subject

Installation of additional instrument panel cooling devices.

I.5 Reason

For better cooling at severely hot climatic conditions the installation of additional instrument panel cooling devices is regulated by this service bulletin.

I.6 Concurrent Documents

None.

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-244, which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

I.8 Accomplishment/Instructions

See Work Instruction WI-OSB-D4-048.

I.9 Mass (Weight) and CG

Negligible

II PLANNING INFORMATION**II.1 Material & Availability**

See WI-OSB-D4-048

II.2 Special Tools

none

II.3 Labor effort

Appr. 4 hr

II.4 Credit

n. a.

II.5 Reference Documents

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue
WI-OSB-D4-048

III REMARKS

1. All measures must be carried out by manufacturer, a certified aircraft station or a certified aircraft mechanic
2. Accomplishment of the measures must be confirmed in the log book.
3. In case of any doubt, contact Diamond Aircraft Industries.