

## TEMPORARY REVISION

### TR-OÄM-40-277/a

supersedes TR-OÄM-40-277

## TURN COORDINATOR 1394T100-12RB

This Temporary Revision TR-OÄM-40-277/a is approved in conjunction with the Optional Design Change Advisory OÄM 40-277/a and is valid in conjunction with the latest revision of the DA 40 or DA 40 D Airplane Flight Manual until this temporary revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

#### Affected Pages:

Doc. No.	Rev.	Page
6.01.01-E	7	6-19b
6.01.05-E	3	6-17d

#### Instruction:

- \* Print this document on yellow paper (single-sided).
- \* Insert the cover page of this Temporary Revision as the first page of the manual.
- \* Insert the other pages of the Temporary Revision in front of the original manual pages.

Doc. No. 6.01.01-E Doc. No. 6.01.05-E	TR-OÄM-40-277/a 22-Sep-2009	Cover page
--	-----------------------------	------------

DA 40 AFM  
DA 40 D AFM



Temporary Revision  
1394T100-12RB

**Affected Chapters:**

**6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY**

*The following item must be added to the Equipment List:*

Airplane Serial No.:		Registration:		Date:	
Description	Type	Part No.:	Manufacturer	S/N	in- stalled
NAVIGATION					
Turn coordinator	1394T100-(12RB)		Mid Continent		

Doc. No. 6.01.01-E  
Doc. No. 6.01.05-E

TR-OÄM-40-277/a 22-Sep-2009

Page 6-19b  
Page 6-17d