

SERVICE INFORMATION No. SI D4-117

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
 - 2) To distribute applicable information/documents from our suppliers to our customers with additional information.
- Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 D airplanes

1.2 Subject:

Proper draining of the fuel system
ATA-Code: 28

1.3 Reason:

Engine failures caused by improper draining of the fuel system during the pre flight inspection.

1.4 Information:

Diamond Aircraft Ind. hereby informs all customers that proper draining of the fuel system is essential to prevent the engine from damage due to water in the fuel system, especially if the engine is operated with Jet Fuel.

Refer also to the instructions given in the Airplane Flight Manual of the DA 40 D.

II. OTHERS

In case of doubt contact Diamond Aircraft Ind.