

OPTIONAL SERVICE BULLETIN

NO. OSB-42-013

I TECHNICAL DETAILS

I.1 Category

Optional

I.2 Airplanes affected

Type: DA 42

Serial Numbers: 42.010 and subsequent

I.3 Time of Compliance

At holder's discretion

I.4 Subject

Installation of an Auxiliary Fuel Tank

ATA-Code: 28-00

I.5 Reason

In order to increase the available fuel tank capacity, this Service Bulletin permits the retrofit installation of an auxiliary fuel tank. At the time being this can solely be carried out by Diamond Aircraft Industries.

I.6 Concurrent Documents

None

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 42-056 latest revision, which has been approved by EASA .

The technical content of this document has been approved und the authority of DOA No. EASA.21J.052.

I.8 Accomplishment/Instructions

Comply with WI OSB-42-013
Make all necessary entries in the airplane logs.
Carry out weighing according to weight and balance report.
Record aircraft empty weight and CG in AFM.

I.9 Mass (Weight) and CG

Mass (Weight) and CG affected.

II PLANNING INFORMATION**II.1 Material & Availability**

See WI OSB-42-013

II.2 Special Tools

None

II.3 Credit

None

II.4 Reference Documents

DA 42 Airplane Maintenance Manual Doc. No. 7.01.01-E
WI OSB-42-013

III REMARKS

In case of doubt, contact Diamond Aircraft.
This Service Bulletin may ONLY be carried out by Diamond Aircraft Industries.