

OPTIONAL SERVICE BULLETIN

NO. OSB-42-018

I TECHNICAL DETAILS

I.1 Category

Optional

I.2 Airplanes affected

Type: DA 42

Serial Numbers: 42.004 and subsequent

I.3 Time of Compliance

At owner's discretion.

I.4 Subject

Installation of a WX-500 Stormscope.

I.5 Reason

This Service Bulletin allows the installation and operation of a WX-500 Stormscope.

I.6 Concurrent Documents

None

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 42-057, which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

The technical content of this document has been approved und the authority of DOA No. EASA.21J.052.

I.8 Accomplishment/Instructions

Comply with WI-OSB-42-018, installation of WX-500 Stormscope.

I.9 Mass (Weight) and CG

Mass and CG are affected (see WI-OSB-42-018)

II PLANNING INFORMATION

II.1 Material & Availability

Materials including drawings are available from Diamond Aircraft Industries

II.2 Special Tools

None

II.3 Credit

None.

II.4 Reference Documents

WI-OSB-42-018 for DA 42.
DA42 Series Airplane Maintenance Manual, Doc. No. 7.02.01, always latest revision.

III REMARKS

1. All measures must be carried out by manufacturer, a certified aircraft station or a certified aircraft mechanic
2. Accomplishment of the measures must be confirmed in the log book.
3. In case of any doubt, contact Diamond Aircraft Industries.