

OPTIONAL SERVICE BULLETIN

OSB 40-069

OSB 40NG-004

OSB D4-078

OSB F4-023

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 40, DA 40 D, DA 40 F, DA 40 NG
Serial numbers: 40.004 and subsequent
D4.001 and subsequent
40.DS001 and subsequent
40.FC001 and subsequent
40.N001 and subsequent

I.3 Date of effectivity

20-Jul-2010

I.4 Time of Compliance

At owner's discretion.

I.5 Subject

Installation of a coated safety walk.

ATA-Code: 11-20

I.6 Reason

An optional painted safety walk for the DA 40 Series has been developed which withstands extreme weather conditions. With this Service Bulletin the retrofit installation of the coated Safety Walk is possible on aircraft already in operation.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-317, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-OSB 40-069 / WI-OSB D4-078 / WI-OSB F4-023 / WI-OSB 40NG-004, latest effective issue.

I.10 Mass (Weight) and CG

Negligible.

II PLANNING INFORMATION**II.1 Material and Availability**

See WI-OSB 40-069 / WI-OSB D4-078 / WI-OSB F4-023 / WI-OSB 40NG-004, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 4 hours.

II.4 Credit

None.

II.5 Reference Documents

Diamond Aircraft 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

Diamond Aircraft 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

III REMARKS

- a) The work must be carried out by a certified aircraft service station or a certified aircraft maintenance mechanic.
- b) All works, particular those that are not especially described in this work instruction, must be carried out in accordance with the referenced maintenance manual.
- c) In case of doubt, contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH
N. A. Otto-Straße 5
A-2700 Wiener Neustadt
Austria

DAI OSB 40-069
DAI OSB 40NG-004
DAI OSB D4-078
DAI OSB F4-023
Page 4 of 4
20-Jul-2010

**EXECUTION REPORT TO
SERVICE BULLETIN
OSB 40-069
OSB 40NG-004
OSB D4-078
OSB F4-023**

AIRPLANE DATA

Airplane Serial Number: _____

Airplane Registration: _____

Airplane Operator: _____

Hours of operation of airplane: _____

No. of landings: _____

Hours of operation-engine _____

Typical operation of airplane: private, club, training, other _____

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to
airworthiness@diamond-air.at