

## TEMPORARY REVISION

### TR-OÄM-42-215

### Removal of Volt / Ammeter on Connector Box

This Temporary Revision TR-OÄM-42-215 is approved in conjunction with the Optional Design Change Advisory OÄM 42-215 and is valid in conjunction with the latest revision of the DA 42 Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
7.01.05-E	9	9-2a

#### **Instruction**

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this Temporary Revision in front of the corresponding AFM pages.

Doc. # 7.01.05-E	TR-OÄM-42-215	05-Sep-2011	Cover Page
------------------	---------------	-------------	------------

DA 42 AFM



Temporary Revision  
Removal of Volt /  
Ammeter on Connector  
Box

## 9.2 LIST OF SUPPLEMENTS

*The following supplement is amended to read:*

Airplane S/N:		Registration:		Date:	
Sup. No.	Title	Rev. No.	Date	applicable	
				YES	NO
M00	DA 42 M	2	05-Sep-2011	<input type="checkbox"/>	<input type="checkbox"/>

Doc. # 7.01.05-E

TR-OÄM-42-215

05-Sep-2011

9 – 2a